



# PLUMMER LEAD WATER TEST RESULTS

May 12th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest Results
PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002649	Utility	2	In custodian closet next to cafeteria(next to the main supply)	WT-042916-2666- A	< 1	WT-042916-2666- B	< 1			
PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002650	Break Room	1	In staff lounge 122	WT-042916-2667- A	< 1	WT-042916-2667- B	< 1			
PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002651	Cooler	1	In hallway adjacent to room 122Low	WT-042916-2668- A	< 1	WT-042916-2668- B	< 1			
PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002652	Cooler	1	In hallway adjacent to room 122RightHigh	WT-042916-2669- A	< 1	WT-042916-2669- B	< 1			
PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002653	Health Suite	1	In health suite	WT-042916-2670- A	< 1	WT-042916-2670- B	< 1			
PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002654	Cooler	1	In auditoriumLeftLow	WT-042916-2671- A	< 1	WT-042916-2671- B	< 1			
PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002655	Cooler	1	In auditoriumRightHigh	WT-042916-2672- A	< 1	WT-042916-2672- B	< 1			
PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002656	Fountain	2	In classroom 201Right	WT-042916-2673- A	< 1	WT-042916-2673- B	< 1			
PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002657	Classroom	2	In classroom 201Left	WT-042916-2674- A	< 1	WT-042916-2674- B	< 1			
PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002658	Fountain	2	In classroom 202Right	WT-042916-2675- A	< 1	WT-042916-2675- B	< 1			
PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002659	Classroom	2	In classroom 202Left	WT-042916-2676- A	< 1	WT-042916-2676- B	< 1			
PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002660	Fountain	2	In classroom 203Right	WT-042916-2677- A	< 1	WT-042916-2677- B	< 1			
PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002661	Classroom	2	In classroom 203Left	WT-042916-2678- A	< 1	WT-042916-2678- B	< 1			
PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002662	Fountain	2	In classroom 204Right	WT-042916-2679- A	< 1	WT-042916-2679- B	< 1			
PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002663	Classroom	2	In classroom 204Left	WT-042916-2680- A	< 1	WT-042916-2680- B	< 1			
PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002664	Fountain	2	In classroom 206Right	WT-042916-2681- A	< 1	WT-042916-2681- B	< 1			
PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002665	Classroom	2	In classroom 206Left	WT-042916-2682- A	< 1	WT-042916-2682- B	< 1			
PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002666	Fountain	2	In classroom 212RightHigh	WT-042916-2683- A	< 1	WT-042916-2683- B	< 1			
PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002667	Classroom	2	In classroom 212Left	WT-042916-2684- A	< 1	WT-042916-2684- B	< 1			
PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002668	Cooler	2	In hallway adjacent to room 217LeftLow	WT-042916-2685- A	< 1	WT-042916-2685- B	< 1			
PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002669	Cooler	2	In hallway adjacent to room 217RightHigh	WT-042916-2686- A	< 1	WT-042916-2686- B	< 1			
PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002670	Fountain	2	In classroom 214Right	WT-042916-2687- A	< 1	WT-042916-2687- B	< 1			
PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002671	Classroom	2	In classroom 214Left	WT-042916-2688- A	< 1	WT-042916-2688- B	< 1			
PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002672	Fountain	2	In classroom 219Right	WT-042916-2689- A	< 1	WT-042916-2689- B	< 1			
PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002673	Classroom	2	In classroom 219	WT-042916-2690- A	< 1	WT-042916-2690- B	< 1			
PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002674	Fountain	2	In classroom 216Right	WT-042916-2691- A	< 1	WT-042916-2691- B	< 1			
PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002675	Classroom	2	In classroom 216Mid	WT-042916-2692- A	< 1	WT-042916-2692- B	< 1			
PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002676	Fountain	2	In classroom 221Right	WT-042916-2693- A	< 1	WT-042916-2693- B	< 1			



# PLUMMER LEAD WATER TEST RESULTS

May 12th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest Results
PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002677	Classroom	2	In classroom 221Left	WT-042916-2694- A	< 1	WT-042916-2694- B	< 1			
PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002678	Fountain	2	In cafeteria	WT-042916-2695- A	< 1	WT-042916-2695- B	< 1			
PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002679	Kitchen	2	In kitchen	WT-042916-2696- A	< 1	WT-042916-2696- B	< 1			
PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002680	Cooler	3	In hallway adjacent to room 309LeftLow	WT-042916-2697- A	< 1	WT-042916-2697- B	< 1			
PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002681	Fountain	3	In hallway adjacent to room 309RightHigh	WT-042916-2698- A	< 1	WT-042916-2698- B	< 1			
PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002682	Classroom	3	In classroom 301Left	WT-042916-2699- A	< 1	WT-042916-2699- B	< 1			
PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002683	Classroom	3	In classroom 301Right	WT-042916-2700- A	< 1	WT-042916-2700- B	< 1			

Footnotes:  
A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.  
B - Second draw sample is collected after a 60 second flush at that device after the first draw.